LCW Small Parts Basket Instructions

1) Remove one strand of wire from the edge of the mesh and set aside for later use or have a piece of stainless steel wire available.
2) Using a wire cutter, remove a 3” square from each corner. See diagram.
3) Fold each side up and use the wire strand or piece of stainless steel wire to tie each corner together.

